BSI-inspectorate America 178 Mortland Road Searsport, Maine 04974 (207)548-6440



QUALITY CERTIFICATE

Vessel Customer

Operation

SHORE TANK NO. 3

SPRAGUE

ANALYSIS

Port Date

Terminal

BUCKSPORT, MAINE March 24, 2003

SPRAGUE

SP/03/0346 Report

Reference

Sample # 287169

Name of material being tested Description of sample source Samples Drawn by (company) Samples Tested by (company)

NO. 6 FUEL OIL 0.5%

EX. SHORE TANK NO. 3 AFTER DISCHARGE OF FLORIDA **INSPECTORATE INSPECTORATE**

Tests being Performed	Test method	Minimum Maximum	Sample Source
	ing pagamaga in a magamagan an a magamagan aka manaya a manaya ka da ka ka mada da d		
GRAVITY, API @ 60 F FLASH POINT, F VISCOSITY, SSF @ 122 F POUR POINT, F WATER & SEDIMENT, % VOL. SULPHUR, % WT. ASH, % WT. VANADIUM, PPM SODIUM, PPM BTU'S/POUND BTU'S/GALLON NITROGEN, % WT. CARBON RESIDUE, % WT. ASPHALTENES, % WT.	ASTM D 4052 ASTM D 93 ASTM D 445/2161 ASTM D 97 ASTM D 1796 ASTM D 4294 ASTM D 482 AA/AE AA/AE CALCULATION CONVERSION ASTM D 3228 ASTM D 4530 IP-143		14.6 200+ 41.9 +37.4 0.25 0.469 0.088 9 11 18,641 150,358 0.335 7.97 2.04
THE ATTACHED CERTIFICATE REPRESENTS THE BY THE INSPECTION SERVICE ON THE DATE STACE THE INSPECTION SERVICE OF THE INSPECTION SERVICE IT MAY SELL FROM SUCH INSPECTION CERTIFICATE BUT SU MEET THE SPECIFICATIONS AS MAY BE REQUIFICED THAT THE PROBLEM THAT THE PROBLEM THAT THE PROBLEM TO THE STATE THAT THE PROBLEM THAT THE PROBLEM THAT THE PROBLEM THAT THE PROBLEM TO THE STATE THAT THE PROBLEM THE PROBLEM THAT THE PROBLEM THE PROBLEM THAT THE PROBLEM THE PROBLEM THE PROBLEM THE THAT THE PROBLEM THE PROBL	ITED ON THE ECTION SERVICE. SPRAGUE AT THE RACK MAY DIFFER CH PRODUCT SHALL. ED BY ANY APPLICABLE		

DENNIS E. CURTIS

Inspectorate America Corp (Searsport, Me.)